## Approved For Release 2000/06/14 DP78-06505A0003001000 6-0

6 JUN 1968

MEMORANDUM FOR THE RECORD

25X1A

A&E DRAWINGS, RECLIVED APR 68

- 1. Subject drawings are so incomplete that the following review cannot be regarded as having significant value. Furthermore, it is anticipated that the A&E contract will be terminated and a new one assigned.
  - 2. Dwg. No. 38-04-100, Sheet 1:
    - a. Graphic scale needed.
    - b. Guardhouse not identified.
  - c. Power house may be improperly oriented, dependent on final determination of truck access to the building.
  - 3. Dwg. No. 38-04-100, Sheet 2:
    - a. Identify "Biological Purification Plant."
    - b. Improper truck access to power plant.
    - c. Sidewalk on south side of entrance road unnecessary.
    - d. Why a sidewalk into the substation.
    - c. Graphic scale needed.
    - f. Location of air conditioning equipment should be shown.
  - 4. Dwg. No. 38-04-100, Sheet 3:
    - a. Exterior door of penthouse not shown in elevation.
    - b. Room 106 should be identified (hallway).
  - c. Sheets 3 and 11 disagree on room numbers (105A vice 106A); also on Room 115 and Room 106 doors.
    - d. Room number required for J. C.
  - 5. Dwg. No. 38-04-100, Sheet 4:
    - a. Sewage tank should be deleted.
  - b. Attention must be directed to possible conflict in siting of air conditioner and underground piping and conduit.
    - c. Power house truck access again.
  - 6. Dwg. No. 38-04-100, Sheet 5:
    - a. Floor drain in depressed floor area?
      - b. Why the elevations no penthouse door?
  - 7. Dwg. No. 38-04-100, Sheet 6:
    - a. Too incomplete; where is vault ventilation?

RECD

C

DC

EX C

C/RE

RO

C/ENG

## Approved For Release 2000/06/14 : CIA-RDP78-05505A000300100076-0

25X1A

SUPERCT:

A&E Drawings, received Apr. 68.

- 8. Dwg. No. 38-04-100, Sheet 9:
- a. Cable entry vault in wrong location; should be on south side. Rearrange cable trenching to agree with proper vault location.
  - b. Con't like crossover of power and rf cable trenches.
- c. Watch for regulations on siting of telephone and nower cable trenches.
- 9. Dwg. No. 38-04-100, Sheet 10:
  - a. Where is generator dummy load (D5322-R/E-02A).
  - b. Watch regulations on power and telephone trenches.
  - c. Does substation get adequate security lighting?
- 10. Dwg. No. 38-04-100, Sheet 11:
  - a. Room 115A and Room 106 doors inconsistent with Sheet 3.
  - b. Provide receptacles in Room 110/105/106 for cleaning devices.
  - c. Prefer fluorescent lighting in Shop and storage areas;

also in other areas where possible to decrease heat load.

- d. Provide a receptacle at the sink in the Men's Room (shaving).
- e. Provide a receptacle in the vault.
- f. Cable entry vault for rf cables in wrong locations.

25X1A

OL/RECD/LB

Distribution:

Original - OL/RECD Official

1 - CC-in

1- OI/RECD/EB Chrono

25X1A

OL/REGD/EE amw/3023(5 June 1968)

2